



Tap conductor to top of horizontal STEEL pipe or flat surface.

Note: For DUCTILE IRON, see page 17.

| Conductor Size | Surface | Welder Part No.† | Welder Price | Weld Metal |
|--|---|------------------|--------------|------------|
| #14 to #10 Solid (use sleeve CAB-133-1H)* or #8 Solid or Stranded, or #6 Solid | Flat (4" & larger pipe) 3/4" to 3-1/2" pipe | CAHAA-1G | CAA | CA15 |
| | | CAHAA-1GA | CAA | CA15 |
| 6 Stranded | Flat (4" & larger pipe) 3/4" to 3-1/2" pipe | CAHAA-1H | CAA | CA15 |
| | | CAHAA-1HA | CAA | CA15 |
| 4 Solid | Flat (6" & larger pipe) 3/4" to 3-1/2" pipe 4" to 5" pipe | CAHAA-1K | CAA | CA15 |
| | | CAHAA-1KA | CAA | CA15 |
| | | CAHAA-1KB | CAA | CA15 |
| 4 Stranded | Flat (6" & larger pipe) 3/4" to 3-1/2" pipe 4" to 5" pipe | CAHAA-1L | CAA | CA15 |
| | | CAHAA-1LA | CAA | CA15 |
| | | CAHAA-1LB | CAA | CA15 |
| 2 Solid | Flat (10" & larger pipe) 1" to 3-1/2" pipe 4" to 8" pipe | CAHAA-1T | CAA | CA25 |
| | | CAHAA-1TA | CAA | CA25 |
| | | CAHAA-1TB | CAA | CA25 |
| 2 Stranded | Flat (16" & larger pipe) 1" to 3-1/2" pipe 4" to 8" pipe 10" to 14" pipe | CAHAA-1V | CAA | CA32 |
| | | CAHAA-1VA | CAA | CA32 |
| | | CAHAA-1VB | CAA | CA32 |
| | | CAHAA-1VC | CAA | CA32 |
| 1 Stranded | Flat (16" & larger pipe) 1-1/2" to 3-1/2" pipe 4" to 8" pipe 10" to 14" pipe | CAHAA-1Y | CAA | CA45 |
| | | CAHAA-1YA | CAA | CA45 |
| | | CAHAA-1YB | CAA | CA45 |
| | | CAHAA-1YC | CAA | CA45 |
| 1/0 Stranded | Flat (20" & larger pipe) 2-1/2" to 3-1/2" pipe 4" to 8" pipe 10" to 18" pipe | CAHAA-2C | CAA | CA65 |
| | | CAHAA-2CA | CAA | CA65 |
| | | CAHAA-2CB | CAA | CA65 |
| | | CAHAA-2CC | CAA | CA65 |
| 2/0 Stranded | Flat (20" & larger pipe) 2-1/2" to 3-1/2" pipe 4" to 8" pipe 10" to 18" pipe | CAHAA-2G | CAA | CA65 |
| | | CAHAA-2GA | CAA | CA65 |
| | | CAHAA-2GB | CAA | CA65 |
| | | CAHAA-2GC | CAA | CA65 |



CAHA - Cable to Horizontal Steel Pipe



CAHA - Cable on surface

*1 sleeve per connection.

† Welder Part No. includes mold frame. If mold only (less frame) is required, order - Welder Part No. - "M".

